

SHN	LxH	200x100	300x100 200x150	400x100 200x200	300x150	500x100	600x100 400x150 300x200	700x100
Q	A _{eff}	0.0088	0.0144	0.0200	0.0228	0.0256	0.0311	0.0367
25	V _k	0.78	0.50					
	X _{0,25}	0.60	0.46					
	P _s	0.26	0.11					
	Lw(A)	<20	<20					
50	V _k	1.57	1.01	0.74	0.65			
	X _{0,25}	1.20	0.93	0.78	0.72			
	P _s	1.04	0.43	0.23	0.18			
	Lw(A)	<20	<20	<20	<20			
75	V _k	2.35	1.51	1.11	0.98	0.88	0.73	
	X _{0,25}	1.80	1.39	1.17	1.09	1.03	0.93	
	P _s	2.33	0.96	0.52	0.41	0.33	0.22	
	Lw(A)	<20	<20	<20	<20	<20	<20	
100	V _k	3.14	2.02	1.49	1.30	1.18	0.97	0.83
	X _{0,25}	2.40	1.86	1.57	1.44	1.38	1.24	1.14
	P _s	4.16	1.72	0.93	0.71	0.59	0.40	0.29
	Lw(A)	22	<20	<20	<20	<20	<20	<20
125	V _k	3.92	2.52	1.86	1.63	1.47	1.22	1.04
	X _{0,25}	3.00	2.32	1.96	1.81	1.72	1.56	1.43
	P _s	6.48	2.68	1.46	1.12	0.91	0.63	0.46
	Lw(A)	26	<20	<20	<20	<20	<20	<20
150	V _k	4.70	3.02	2.23	1.96	1.76	1.46	1.25
	X _{0,25}	3.60	2.78	2.35	2.18	2.06	1.87	1.72
	P _s	9.32	3.85	2.10	1.62	1.30	0.90	0.66
	Lw(A)	30	20	<20	<20	<20	<20	<20
200	V _k	6.27	4.03	2.97	2.61	2.35	1.95	1.66
	X _{0,25}	4.80	3.71	3.13	2.90	2.75	2.49	2.29
	P _s	16.58	6.85	3.72	2.87	2.33	1.63	1.62
	Lw(A)	35	25	22	<20	<20	<20	<20
250	V _k	7.84	5.04	3.71	3.26	2.94	2.43	2.08
	X _{0,25}	6.00	4.64	3.91	3.62	3.44	3.11	2.87
	P _s	25.92	10.71	5.81	4.48	3.65	2.49	1.82
	Lw(A)	41	31	26	21	<20	<20	<20
300	V _k	9.41	6.05	4.46	3.91	3.53	2.92	2.49
	X _{0,25}	7.20	6.99	4.70	4.34	4.13	3.73	3.43
	P _s	37.35	15.44	8.39	6.45	5.26	3.60	2.61
	Lw(A)	45	35	31	26	23	21	<20



SHN	LxH	200x100	300x100 200x150	400x100 200x200	300x150	500x100	600x100 400x150 300x200	700x100
Q	A _{eff}	0.0088	0.0144	0.0200	0.0228	0.0256	0.0311	0.0367
400	V _k	12.55	8.07	5.94	5.21	4.70	3.89	3.32
	X _{0,25}	9.60	7.43	6.26	5.78	5.51	4.97	4.57
	P _s	66.43	27.47	14.88	11.45	9.32	6.38	4.65
	Lw(A)	53	42	37	34	31	27	23
600	V _k		12.10	8.91	7.82	7.06	5.84	4.98
	X _{0,25}		11.13	9.38	8.68	8.27	7.47	6.86
	P _s		61.75	33.48	25.79	21.02	14.38	10.46
	Lw(A)		53	47	43	41	37	34
800	V _k			11.89	10.43	9.41	7.79	6.64
	X _{0,25}			12.52	11.58	11.02	9.96	9.15
	P _s			59.62	45.88	37.35	25.60	18.59
	Lw(A)			54	51	48	44	41
1000	V _k					11.76	9.73	8.30
	X _{0,25}					13.77	12.44	11.44
	P _s					58.33	39.93	29.05
	Lw(A)					54	50	46
1200	V _k						11.68	9.96
	X _{0,25}						14.93	13.72
	P _s						57.54	41.84
	Lw(A)						55	51
1600	V _k							13.28
	X _{0,25}							18.30
	P _s							74.38
	Lw(A)							58
2000	V _k							
	X _{0,25}							
	P _s							
	Lw(A)							
2400	V _k							
	X _{0,25}							
	P _s							
	Lw(A)							
2800	V _k							
	X _{0,25}							
	P _s							
	Lw(A)							



SHN	LxH	500x150	400x200 800x100	600x150 300x300	500x200 1000x100	700x150	800x150 600x200 400x300 1200x100	700x200
Q	A _{eff}	0.0395	0.0423	0.0479	0.0534	0.0562	0.0646	0.0757
25	V _k							
	X _{0,25}							
	P _s							
	Lw(A)							
50	V _k							
	X _{0,25}							
	P _s							
	Lw(A)							
75	V _k							
	X _{0,25}							
	P _s							
	Lw(A)							
100	V _k	0.76						
	X _{0,25}	1.07						
	P _s	0.24						
	Lw(A)	<20						
125	V _k	0.95	0.83	0.79				
	X _{0,25}	1.34	1.29	1.35				
	P _s	0.38	0.29	0.26				
	Lw(A)	<20	<20	<20				
150	V _k	1.14	0.99	0.94	0.78	0.81	0.65	
	X _{0,25}	1.61	1.54	1.61	1.35	1.50	1.23	
	P _s	0.55	0.41	0.37	0.26	0.28	0.18	
	Lw(A)	<20	<20	<20	<20	<20	<20	
200	V _k	1.52	1.32	1.26	1.05	1.07	0.87	0.74
	X _{0,25}	2.15	2.06	2.16	1.82	1.98	1.65	1.59
	P _s	0.97	0.73	0.67	0.46	0.48	0.32	0.23
	Lw(A)	<20	<20	<20	<20	<20	<20	<20
250	V _k	1.90	1.65	1.57	1.31	1.34	1.08	0.92
	X _{0,25}	2.68	2.57	2.69	2.27	2.47	2.05	1.97
	P _s	1.52	1.15	1.04	0.72	0.76	0.49	0.36
	Lw(A)	<20	<20	<20	<20	<20	<20	<20
300	V _k	2.28	1.98	1.89	1.57	1.61	1.30	1.11
	X _{0,25}	3.22	3.09	3.24	2.72	2.97	2.46	2.38
	P _s	2.19	1.65	1.51	1.04	1.09	0.71	0.52
	Lw(A)	<20	<20	<20	<20	<20	<20	<20



SHN	LxH	500x150	400x200 800x100	600x150 300x300	500x200 1000x100	700x150	800x150 600x200 400x300 1200x100	700x200
Q	A _{eff}	0.0395	0.0423	0.0479	0.0534	0.0562	0.0646	0.0757
400	V _k	3.04	2.64	2.52	2.09	2.15	1.73	1.48
	X _{0,25}	4.29	4.12	4.32	3.63	3.97	3.28	3.17
	P _s	3.90	2.94	2.68	1.84	1.95	1.26	0.92
	Lw(A)	23	<20	<20	<20	<20	<20	<20
600	V _k	4.56	3.96	3.78	3.14	3.22	2.60	2.21
	X _{0,25}	6.44	6.18	6.48	5.45	5.95	4.93	4.74
	P _s	8.77	6.61	6.03	4.16	4.37	2.85	2.06
	Lw(A)	32	32	31	27	25	23	<20
800	V _k	6.08	5.28	5.03	4.18	4.29	3.46	2.95
	X _{0,25}	8.59	8.24	8.62	7.25	7.92	6.55	6.32
	P _s	15.59	11.76	10.67	7.37	7.76	5.05	3.67
	Lw(A)	39	39	37	34	32	30	26
1000	V _k	7.60	6.60	6.29	5.23	5.37	4.33	3.69
	X _{0,25}	10.74	10.30	10.78	9.08	9.91	8.20	7.91
	P _s	24.36	18.37	16.69	11.54	12.16	7.91	5.74
	Lw(A)	44	44	43	40	38	35	33
1200	V _k	9.13	7.92	7.55	6.27	6.44	5.19	4.43
	X _{0,25}	12.90	12.36	12.94	10.88	11.89	9.83	9.49
	P _s	35.16	26.45	24.04	16.58	17.49	11.36	8.28
	Lw(A)	49	49	47	44	42	40	37
1600	V _k	12.17	10.57	10.07	8.36	8.59	6.92	5.90
	X _{0,25}	17.19	16.49	17.26	14.51	15.86	13.11	12.64
	P _s	62.46	47.12	42.77	29.48	31.12	20.20	14.68
	Lw(A)	56	57	55	52	49	47	44
2000	V _k				10.46	10.74	8.65	7.38
	X _{0,25}				18.15	19.83	16.39	15.82
	P _s				46.14	48.65	31.56	22.97
	Lw(A)				58	55	53	50
2400	V _k							8.86
	X _{0,25}							18.99
	P _s							33.11
	Lw(A)							55
2800	V _k							
	X _{0,25}							
	P _s							
	Lw(A)							



SHN	LxH	500x300 1000x150	800x200 400x400	1200x150 600x300	1000x200 500x400	700x300	500x500	1200x200 800x300 600x400
Q	A _{eff}	0.0813	0.0869	0.9800	0.1092	0.1147	0.1370	0.1410
25	V _k							
	X _{0,25}							
	P _s							
	Lw(A)							
50	V _k							
	X _{0,25}							
	P _s							
	Lw(A)							
75	V _k							
	X _{0,25}							
	P _s							
	Lw(A)							
100	V _k							
	X _{0,25}							
	P _s							
	Lw(A)							
125	V _k							
	X _{0,25}							
	P _s							
	Lw(A)							
150	V _k							
	X _{0,25}							
	P _s							
	Lw(A)							
200	V _k							
	X _{0,25}							
	P _s							
	Lw(A)							
250	V _k	0.84	0.80					
	X _{0,25}	1.89	1.88					
	P _s	0.30	0.27					
	Lw(A)	<20	<20					
300	V _k	1.01	0.97	0.83	0.77	0.71		
	X _{0,25}	2.28	2.28	2.04	2.02	1.93		
	P _s	0.43	0.40	0.29	0.25	0.21		
	Lw(A)	<20	<20	<20	<20	<20		



SHN	LxH	500x300 1000x150	800x200 400x400	1200x150 600x300	1000x200 500x400	700x300	500x500	1200x200 800x300 600x400
Q	A _{eff}	0.0813	0.0869	0.9800	0.1092	0.1147	0.1370	0.1410
400	V _k	1.34	1.29	1.11	1.02	0.95	0.78	0.83
	X _{0,25}	3.02	3.03	2.73	2.68	2.59	2.35	2.46
	P _s	0.76	0.70	0.52	0.44	0.38	0.26	0.29
	Lw(A)	<20	<20	<20	<20	<20	<20	<20
600	V _k	2.02	1.93	1.67	1.54	1.42	1.18	1.24
	X _{0,25}	4.55	4.54	4.11	4.04	3.87	3.54	3.67
	P _s	1.72	1.57	1.18	1.00	0.85	0.59	0.65
	Lw(A)	<20	<20	<20	<20	<20	<20	<20
800	V _k	2.69	2.57	2.22	2.05	1.90	1.57	1.65
	X _{0,25}	6.06	6.05	5.46	5.38	5.18	4.71	4.88
	P _s	3.05	2.79	2.08	1.77	1.52	1.04	1.15
	Lw(A)	24	23	21	<20	<20	<20	<20
1000	V _k	3.36	3.22	2.78	2.56	2.37	1.96	2.07
	X _{0,25}	7.57	7.57	6.84	6.72	6.46	5.88	6.13
	P _s	4.76	4.37	3.26	2.76	2.37	1.62	1.81
	Lw(A)	31	30	26	24	24	22	21
1200	V _k	4.03	3.86	3.34	3.07	2.85	2.35	2.48
	X _{0,25}	9.08	9.08	8.22	8.05	7.77	7.05	7.34
	P _s	6.85	6.28	4.70	3.97	3.43	2.33	2.59
	Lw(A)	35	34	31	30	29	25	25
1600	V _k	5.38	5.15	4.45	4.10	3.80	3.14	3.31
	X _{0,25}	12.13	12.11	10.95	10.76	10.35	9.43	9.80
	P _s	12.21	11.19	8.35	7.09	6.09	4.16	4.62
	Lw(A)	42	41	38	36	36	32	32
2000	V _k	6.72	6.43	5.56	5.12	4.74	3.92	4.14
	X _{0,25}	15.15	15.12	13.68	13.43	12.92	11.77	12.25
	P _s	19.05	17.44	13.04	11.06	9.48	6.48	7.23
	Lw(A)	47	46	43	42	41	36	38
2400	V _k	8.07	7.72	6.67	6.15	5.69	4.70	4.96
	X _{0,25}	18.19	18.16	16.41	16.13	15.50	14.11	14.68
	P _s	27.47	25.14	18.76	15.95	13.65	9.32	10.38
	Lw(A)	52	51	48	46	45	41	42
2800	V _k	9.41	9.01	7.79	7.17	6.64	5.49	5.79
	X _{0,25}	21.21	21.19	19.17	18.81	18.09	16.48	17.14
	P _s	37.35	34.24	25.59	21.68	18.59	12.71	14.14
	Lw(A)	57	56	52	51	49	45	46



SHN	LxH	500x300 1000x150	800x200 400x400	1200x150 600x300	1000x200 500x400	700x300	500x500	1200x200 800x300 600x400
Q	A _{eff}	0.0813	0.0869	0.9800	0.1092	0.1147	0.1370	0.1410
3200	V _k				8.90	8.19	7.59	6.27
	X _{0,25}				21.90	21.48	20.68	18.82
	P _s				33.41	28.28	24.30	16.58
	Lw(A)				56	55	53	48
3600	V _k							6.62
	X _{0,25}							19.59
	P _s							18.48
	Lw(A)							49
4000	V _k							6.62
	X _{0,25}							19.59
	P _s							18.48
	Lw(A)							49
4500	V _k							6.62
	X _{0,25}							19.59
	P _s							18.48
	Lw(A)							49
5000	V _k							6.62
	X _{0,25}							19.59
	P _s							18.48
	Lw(A)							49
5500	V _k							6.62
	X _{0,25}							19.59
	P _s							18.48
	Lw(A)							49
6000	V _k							6.62
	X _{0,25}							19.59
	P _s							18.48
	Lw(A)							49



SHN	LxH	700x400	1000x300 600x500	800x400	1200x300	800x500 1000x400	1200x400	1000x500
Q	A _{eff}	0.1537	0.1649	0.1760	0.2030	0.2206	0.2758	0.2764
400	V _k	0.70	0.66					
	X _{0,25}	2.22	2.18					
	P _s	0.21	0.18					
	Lw(A)	<20	<20					
600	V _k	1.05	0.99	0.91	0.82	0.73		
	X _{0,25}	3.33	3.27	3.08	2.96	2.76		
	P _s	0.46	0.41	0.35	0.28	0.22		
	Lw(A)	<20	<20	<20	<20	<20		
800	V _k	1.40	1.32	1.22	1.09	0.97	0.81	0.77
	X _{0,25}	4.44	4.36	4.13	3.93	3.66	3.35	3.24
	P _s	0.83	0.73	0.63	0.50	0.40	0.28	0.25
	Lw(A)	<20	<20	<20	<20	<20	<20	<20
1000	V _k	1.75	1.65	1.52	1.37	1.21	1.01	0.96
	X _{0,25}	5.56	5.45	5.15	4.95	4.57	4.17	4.03
	P _s	1.29	1.15	0.97	0.79	0.62	0.43	0.39
	Lw(A)	<20	<20	<20	<20	<20	<20	<20
1200	V _k	2.10	1.98	1.83	1.64	1.46	1.21	1.15
	X _{0,25}	6.67	6.54	6.20	5.92	5.52	5.00	4.83
	P _s	1.86	1.65	1.41	1.34	0.90	0.62	0.56
	Lw(A)	21	21	21	<20	<20	<20	<20
1600	V _k	2.80	2.63	2.44	2.19	1.94	1.61	1.54
	X _{0,25}	8.89	8.68	8.27	7.91	7.33	6.65	6.47
	P _s	3.31	2.92	2.51	2.02	1.59	1.09	1.00
	Lw(A)	29	28	27	24	22	<20	<20
2000	V _k	3.50	3.29	3.05	2.73	2.43	2.01	1.92
	X _{0,25}	11.11	10.86	10.33	9.85	9.18	8.30	8.07
	P _s	5.17	4.57	3.92	3.14	2.49	1.70	1.55
	Lw(A)	34	33	32	29	27	23	22
2400	V _k	4.20	3.95	3.66	3.28	2.91	2.42	2.30
	X _{0,25}	13.33	13.04	12.40	11.84	10.99	10.00	9.66
	P _s	7.44	6.58	5.65	4.54	3.57	2.47	2.23
	Lw(A)	39	38	36	33	32	27	26
2800	V _k	4.89	4.61	4.27	3.83	3.40	2.82	2.69
	X _{0,25}	15.52	15.22	14.47	13.83	12.85	11.65	11.30
	P _s	10.08	8.96	7.70	6.19	4.88	3.35	3.05
	Lw(A)	43	42	40	37	35	31	30



SHN	LxH	700x400	1000x300 600x500	800x400	1200x300	800x500 1000x400	1200x400	1000x500
Q	A _{eff}	0.1537	0.1649	0.1760	0.2030	0.2206	0.2758	0.2764
3200	V _k	5.59	5.27	4.88	4.37	3.88	3.22	3.07
	X _{0,25}	17.75	17.40	16.53	15.77	14.66	13.30	12.90
	P _s	13.18	11.71	10.04	8.05	6.35	4.37	3.97
	Lw(A)	46	45	43	41	39	34	33
3600	V _k	6.29	5.93	5.49	4.92	4.37	3.63	3.46
	X _{0,25}	19.97	19.57	18.60	17.76	16.51	15.00	14.54
	P _s	16.69	14.83	12.71	10.21	8.05	5.56	5.05
	Lw(A)	49	48	46	43	42	37	36
4000	V _k	6.99	6.58	6.10	5.47	4.85	4.03	3.84
	X _{0,25}	22.19	21.72	20.67	19.75	18.32	16.65	16.13
	P _s	20.61	18.26	15.69	12.62	9.92	6.85	6.22
	Lw(A)	52	51	49	46	44	40	38
4500	V _k	7.87	7.41	6.86	6.15	5.46	4.53	4.32
	X _{0,25}	24.99	24.46	23.24	22.20	20.63	18.72	18.15
	P _s	26.12	23.16	19.85	15.95	12.57	8.65	7.87
	Lw(A)	55	54	52	49	47	43	42
5000	V _k	8.74	8.23	7.62	6.84	6.06	5.04	4.80
	X _{0,25}	27.75	27.17	25.81	24.69	22.89	20.82	20.17
	P _s	32.22	28.57	24.49	19.73	15.49	10.71	9.72
	Lw(A)	58	57	55	52	50	45	44
5500	V _k					6.67	5.54	5.28
	X _{0,25}					25.20	22.89	22.19
	P _s					18.76	12.94	11.76
	Lw(A)					53	47	46
6000	V _k					7.28	6.04	5.76
	X _{0,25}					27.50	24.95	24.20
	P _s					22.35	15.39	13.99
	Lw(A)					56	50	48

